



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit www.iecex.com

QAR Ref. No.: **GB/SIR/QAR13.0004/07** Page 1 of 1

QAR Free Ref. No.: **80101517 - 80101518** Status:**Issued**

Details of change: Recertification Audit Date of issue:**2021-11-16**

Site(s) audited: **OleumTech Corporation** Valid until:**2024-11-07**
19762 Pauling
Foothill Ranch, CA 92610 USA
United States of America Audit date:**2021-10-15**

Issuing ExCB: **CSAE - CSA Group Testing UK Ltd**

Manufacturer: **OleumTech Corporation**
19762 Pauling
Foothill Ranch, CA 92610
USA

Location of Manufacturer: **United States of America**

Product information: SM, LM, & WT Series Wireless Transmitter
BM Series WIO Modules
WG Series Wireless Gateways
WM Series Wireless Modules
WM Series Expansion IO Modules

Protection concept: **Ex ia, nA, nC, d, t**

Related QARs:

GB/SIR/QAR13.0004/00	GB/SIR/QAR13.0004/01	GB/SIR/QAR13.0004/02
GB/SIR/QAR13.0004/03	GB/SIR/QAR13.0004/04	GB/SIR/QAR13.0004/05
GB/SIR/QAR13.0004/06		

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEX ETL 15.0039X issue: 0	IECEX ETL 15.0039X issue: 1	IECEX FMG 14.0001X issue: 0
IECEX FMG 14.0001X issue: 1	IECEX FMG 14.0001X issue: 2	IECEX FMG 14.0001X issue: 3
IECEX SIR 13.0054X issue: 0	IECEX SIR 13.0054X issue: 1	IECEX SIR 13.0054X issue: 2
IECEX SIR 13.0054X issue: 3	IECEX SIR 13.0054X issue: 4	IECEX SIR 13.0054X issue: 5
IECEX SIR 13.0055X issue: 0	IECEX SIR 13.0055X issue: 1	IECEX SIR 13.0055X issue: 2
IECEX SIR 13.0055X issue: 3	IECEX SIR 15.0055X issue: 0	IECEX SIR 15.0055X issue: 1
IECEX SIR 16.0079X issue: 0	IECEX SIR 16.0079X issue: 1	IECEX SIR 16.0079X issue: 2
IECEX SIR 18.0002X issue: 0	IECEX SIR 18.0002X issue: 1	IECEX SIR 18.0002X issue: 2
IECEX TUR 19.0035 issue: 0	IECEX TUR 19.0036 issue: 0	IECEX TUR 19.0037 issue: 0

Comments: